

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 11/6/2014	Time: 10:07 AM	
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300		
Address of School Corporation: 5808 E Administration Rd			
City: Marengo	Zip: 47140	County Number: 13	
VIN: 1HVBBAAP0XH648402	License Number: 16385	Bus Number: 51	
Make of Body: AmTran	Year: 1999	Make of Chassis: IC Corporation	Year: 1999
Bus Type: C	Mileage: 160642		
Inspection Status: R	Inspected By: Travis Coryea	PE: 5892	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).
64-1-1	Lens is cracked, broken or discolored
63-1-2	A lens is cracked, missing or wrong color

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.