

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 11/7/2014 **Time:** 11:15 AM
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP **Corp ID:** 454600
Address of School Corporation: 6601 Delaware St
City: Merrillville **Zip:** 46410 **County Number:** 45
VIN: 4DRBUAAN3DB255535 **License Number:** 3689 **Bus Number:** 4
Make of Body: IC Corporation **Year:** 2013 **Make of Chassis:** IC Corporation **Year:** 2013
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Dale Morgan **PE:** 4743

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.