

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|------------------------------|-----------------|--------------|------------------|--------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 11/18/2014 | Time: | 2:01 PM |
| Name of School Corporation: | M.S.D. WABASH COUNTY SCHOOLS | Corp ID: | 858050 | | |
| Address of School Corporation: | 204 N 300 W | | | | |
| City: | Wabash | Zip: | 46992 | County Number: | 85 |
| VIN: | 4UZAACT86CU74006 | License Number: | 20756 | Bus Number: | 26 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2006 | Make of Chassis: | Freightliner |
| Bus Type: | C | Mileage: | 129441 | Year: | 2006 |
| Inspection Status: | O | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 33-1-1 | Headlight is inoperative. |
| 69-1-3 | There are breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 21-2-1 | There are missing or broken motor mounts. |
| 62-2-3 | Tire is flat |
| 30-2-1 | Frame is deteriorated, cracked, broken or severely bent. |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.