REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	11/19/2014	**Time:**	9:45 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1HVBBAAP11H370584	**License Number:**	17769	**Bus Number:**	9
Make of Body:	Carpenter **Year:** 2001	**Make of Chassis:**	IC Corporation	**Year:**	2001
Bus Type:	C	**Mileage:**	273533		
Inspection Status:	R	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
19-1-8	If required, positive door opening device is missing or fails to operate properly.
112-1-1	Does not have interior lights that are automatically or manually activated, sufficiently illuminate the lift area, and are activated from the door area

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.