## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Post-Crash Inspec	tion		Date:	11/25/2014	Time:	9:29 AM
Name of School	•	CLIN		E SCHOOL COR	RP.	Corp ID:	121160
Address of School Corporation:			4431 W SR				
City:	Frankfort		Zip:	46041		County Number:	12
VIN:	1BABNCKA15F22	5298		License Number:	20409	Bus Number:	8
Make of Body:	Blue Bird Corporation	Year:	2005	Make of Chassis:	Blue Bird Corporation	Year:	2005
Bus Type:	D			Mileage:	113418		
Inspection Status:	A		Inspected By:	Nate King		PE:	7421

## **Violations - Rejected**

Inspection Code	<b>Description</b>
21-1-1	A dripping oil or fluid leak.

## Violations - Out of Service

Inspection Code	Description
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.