## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:12/2/2014Time:8:23 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:1HVBBABP5XH208769License Number:B518DBus Number:26Make of Body:IC Corporation Year:1999
Make of Chassis: IC Corporation Year:

Bus Type: C Mileage: 115360

Inspection Status: A Inspected By: Travis Coryea PE: 5892

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.