

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 1/5/2015	Time: 4:24 PM
Name of School Corporation: CENTERVILLE-ABINGTON COMM SCHS	Corp ID: 898360	
Address of School Corporation: 116 W SOUTH ST		
City: CENTERVILLE	Zip: 47330	County Number: 89
VIN: 4DRUAAN6BB2662491	License Number: 74506	Bus Number: 7
Make of Body: IC Corporation	Year: 2011	Make of Chassis: IC Corporation
Year: 2009	Mileage: 51000	
Bus Type: C		PE: 8139
Inspection Status: O	Inspected By: Jeremy Mason	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-2	ABS warning light is illuminated
64-1-4	Any front turn signal does not function properly
35-1-1	A heater motor is not operating properly
41-1-3	There is loose or unprotected wiring in passenger area
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
70-1-11	If any window does not meet the optional criteria
40-1-2	Any required instrument or gauge is inoperative. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)
29-1-1	The flooring is improper
61-1-4	There is an air leak from any hose, line, tank, bag, or other component of an air suspension system
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
20-1-5	Door glass is chipped, or cracked
20-1-6	Required padding is missing
17-1-2	Any dome light lens is missing

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

46-2-2	Any seat is broken or not attached to the floor
59-2-4	Stop arm does not function properly
51-2-1	The service door does not open or close properly
34-2-1	Both lamps are inoperative on low beam
62-2-1	Two (2) or more taillights or brake lights do not function
65-2-1	Warning lights fail to operate correctly
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
71-2-1	Insulation is missing from any wire

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.