

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/6/2015	<b>Time:</b>	2:28 PM
<b>Name of School Corporation:</b>	EASTERN GREENE SCHOOLS	<b>Corp ID:</b>	282940		
<b>Address of School Corporation:</b>	RR 4 Box 351				
<b>City:</b>	Bloomfield	<b>Zip:</b>	47424	<b>County Number:</b>	28
<b>VIN:</b>	1GBL7T1D7XJ105333	<b>License Number:</b>	B998F	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	1999	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	1999	<b>Year:</b>	1999	<b>Mileage:</b>	128656
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473
<b>Inspection Status:</b>	R				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**