

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/12/2015 **Time:** 1:52 PM
Name of School Corporation: MILAN COMMUNTIY SCHOOLS **Corp ID:** 696910
Address of School Corporation: 412 E Carr St
City: Milan **Zip:** 47031 **County Number:** 69
VIN: 1GB3G2BG0B1117545 **License Number:** 2906 **Bus Number:** A4
Make of Body: Chevrolet **Year:** 2011 **Make of Chassis:** Collins Bus Corporation **Year:** 2011
Bus Type: A1 **Mileage:** 25407
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.