

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	1/14/2015	Time:	9:53 AM
Name of School Corporation:	CAROUSEL PLAY & LEARN CENTER	Corp ID:	420002		
Address of School Corporation:	900 E. Montgomery Rd.				
City:	Greensburg	Zip:	47240	County Number:	16
VIN:	1GBHG31RX11215706	License Number:	B658BU	Bus Number:	1
Make of Body:	Collins Bus Corporation	Year:	2001	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	47474	Year:	2001
Inspection Status:	R	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.