

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	1/14/2015	<b>Time:</b>	10:16 AM
<b>Name of School Corporation:</b>	SCHOOL CITY OF MISHAWAKA			<b>Corp ID:</b>	717200
<b>Address of School Corporation:</b>	1402 S Main St				
<b>City:</b>	Mishawaka	<b>Zip:</b>	46544	<b>County Number:</b>	71
<b>VIN:</b>	1GBHG31R611197639	<b>License Number:</b>	42697	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2001	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2001	<b>Mileage:</b>	96538	<b>Year:</b>	2001
<b>Bus Type:</b>		<b>Mileage:</b>	96538		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Travis Harrold	<b>PE:</b>	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
4-1-1	The air horn is not properly mounted.
42-1-1	The interior rearview mirror is missing, cracked or discolored

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
4-1-1	The air horn is not properly mounted.
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

### Bus Type Description