REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	1/14/2015	**Time:**	10:16 AM
Name of School Corporation:	SCHOOL CITY OF MISHAWAKA			**Corp ID:**	717200
Address of School Corporation:	1402 S Main St				
City:	Mishawaka	**Zip:**	46544	**County Number:**	71
VIN:	1GBHG31R611197639	**License Number:**	42697	**Bus Number:**	6
Make of Body:	Chevrolet **Year:** 2001	**Make of Chassis:**	Chevrolet	**Year:**	2001
Bus Type:		**Mileage:**	96538		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
4-1-1	The air horn is not properly mounted.
42-1-1	The interior rearview mirror is missing, cracked or discolored

Violations - Out of Service

Inspection Code	Description
4-1-1	The air horn is not properly mounted.
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description