

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 1/14/2015	Time: 9:53 AM
Name of School Corporation: CAROUSEL PLAY & LEARN CENTER	Corp ID: 420002	
Address of School Corporation: 900 E. Montgomery Rd.		
City: Greensburg	Zip: 47240	County Number: 16
VIN: 1GBHG31RX11215706	License Number: B658BU	Bus Number: 1
Make of Body: Collins Bus Corporation	Year: 2001	Make of Chassis: Chevrolet
Year: 2001		
Bus Type: A1	Mileage: 47474	
Inspection Status: R	Inspected By: Chris Clark	PE: 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**