

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/15/2015 **Time:** 6:53 PM
Name of School Corporation: RIVER FOREST COMM. SCHOOL CORP **Corp ID:** 454590
Address of School Corporation: 3250 Michigan St
City: Hobart **Zip:** 46342 **County Number:** 45
VIN: 4DRBWAARX6A987523 **License Number:** 20711 **Bus Number:** 12
Make of Body: IC Corporation **Year:** 2006 **Make of Chassis:** IC Corporation **Year:** 2006
Bus Type: D **Mileage:** 79656
Inspection Status: O **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
7-1-1	Any push-rod travel measures less than 1/4 inch beyond the readjustment limit
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.