## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	1/20/2015	Time:	1:36 PM
Name of School Address of Scho	•	FRANKFORT CO 50 S Maish		OOLS	Corp ID:	121170
City:	Frankfort	Zip:	46041		County Number:	12
VIN:	1BABKCKH66F23	7387	License Number:	21359	Bus Number:	16
Make of Body:	Blue Bird Corporation	<b>Year:</b> 2006	Make of Chassis:	Blue Bird Corporation	Year:	2006
Bus Type:	D		Mileage:	112831		
Inspection Status:	0	Inspected By:	Nate King		PE:	7421

## Violations - Rejected

<u>Inspection</u>	Description
<u>Code</u>	<u>Description</u>

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

## **Violations - Out of Service**

Inspection

<u>Code</u>	<u>Description</u>			
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half $(\hat{A}\frac{1}{2})$ inch in diameter.			

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.