REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	1/21/2015	**Time:**	8:51 AM
Name of School Corporation:		DECATUR COUNTY COMM. SCHOOL				**Corp ID:**	161655
Address of School Corporation:		1645 W SR 46					
City:	Greensburg	**Zip:**	47240			**County Number:**	16
VIN:	1HVBBAATXSH202959			**License Number:**	B700B	**Bus Number:**	37
Make of Body:	Thomas Built Buses, Inc.	**Year:**	1995	**Make of Chassis:**	IC Corporation	**Year:**	1995
Bus Type:	C			**Mileage:**	151606		
Inspection Status:	O	**Inspected By:**	Chris Clark			**PE:**	6665

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
8-2-8	The electric power assist motor fails to operate
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.