REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	1/23/2015	Time:	9:17 AM
Name of School C Address of School	•	DECA	ATUR COUNT` 1645 W SR 4	Y COMM. SCHOC 6)L	Corp ID:	161655
City:	Greensburg		Zip:	47240		County Number:	16
VIN:	1HVBBABP7XH240	574		License Number:	B839G	Bus Number:	34
Make of Body:	Blue Bird Corporation	Year:	1999	Make of Chassis:	IC Corporation	Year:	1999
Bus Type:	С			Mileage:	168235		
Inspection Status:	: 0		Inspected By:	Chris Clark		PE:	6665

Violations - Rejected

Inspection Code	<u>Description</u>
25-1-1	Mirror or mirror backs that are loose or improperly mounted
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
37-1-1	The horn does not operate at all
40-1-2	Any required instrument or gauge is inoperative. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge)

Violations - Out of Service

Inspection Code	Description
IIISDECTION CODE	Describuon

8-2-8 The electric power assist motor fails to operate

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.