

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/27/2015	Time:	8:54 AM		
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.			Corp ID:	454615		
Address of School Corporation:	8855 Wicker Ave						
City:	St John	Zip:	46373	County Number:	45		
VIN:	4DRBUSKN3EB418352		License Number:	731523	Bus Number:	11	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	C			Mileage:	23677		
Inspection Status:	O	Inspected By:	Dale Morgan	PE:	4743		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
55-2-3	Any steering component jams or inhibits safe movement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.