REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:1/29/2015Time:9:13 AMName of School Corporation:AVON COMMUNITY SCHOOLSCorp ID:323315

Address of School Corporation: 7203 E HWY 36

City:AvonZip:46123County Number:32VIN:4DRBRABN52B947079License Number:18818Bus Number:92Make of Body:AmTran Year:2002Make of Chassis:IC Corporation Year:2002

Bus Type: C Mileage: 88434

Inspection Status: O Inspected By: John Pang PE: 6196

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

7-2-3 The required low air-pressure warning device fails to operate properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.