## REPORT OF SCHOOL BUS INSPECTION

Type of 3:26 Post-Crash Inspection Date: 2/5/2015 Time: Inspection: PM M.S.D. MARTINSVILLE SCHOOLS 555925 Name of School Corporation: Corp ID: **Address of School Corporation:** PO Box 1416 County City: Martinsville Zip: 46151 55 Number: License VIN: 4UZABRDJ28CZ15122 B770G Bus Number: 15 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2008 Chassis: Inc. **Bus Type:** С Mileage: 90849 Inspection Inspected 0 PE: Mark Raper 6473 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

**Violations - Out of Service** 

Inspection Code Description

There is body damage which could cause injury to persons near the bus (e.g. jagged 24-2-1 metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.