## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Post-Crash Inspection		Date:	2/11/2015	Time:	10:17 AM
Name of Schoo Address of Sch	I Corporation: MA		SCHOOL CORPO awtown Pike	ORATION	Corp ID:	525615
City:	Bunker Hill	Zip:	46914		County Number:	52
VIN:	1T88Y9D25H1113605		License Number:		Bus Number:	32
Make of Body:	Thomas Built Buses, Yea	ar: 2017	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2017
Bus Type:	D		Mileage:	125468		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

## **Violations - Rejected**

Inspection <u>Code</u>	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
2-1-3	Any back-up light lens is cracked, broken, faded or missing
2-1-1	Required back-up lights do not function.
23-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body
70-1-7	Any emergency window is too difficult to open
62-1-2	One (1) taillight or one (1) brake light does not function

## Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
20-2-2	Door glass is missing

## Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus,

behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.