

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/11/2015	Time:	10:17 AM
Name of School Corporation:	MACONAQUAH SCHOOL CORPORATION			Corp ID:	525615
Address of School Corporation:	7932 S Strawtown Pike				
City:	Bunker Hill	Zip:	46914	County Number:	52
VIN:	1T88Y9D25H1113605	License Number:		Bus Number:	32
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:		Year:	2017
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
2-1-3	Any back-up light lens is cracked, broken, faded or missing
2-1-1	Required back-up lights do not function.
23-1-6	Tailpipe does not extend to, or extends beyond the perimeter of the bus body
70-1-7	Any emergency window is too difficult to open
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
20-2-2	Door glass is missing

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.