

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	2/23/2015	Time:	10:33 AM		
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600		
Address of School Corporation:	6109 Squire Place						
City:	Aurora	Zip:	47001	County Number:	15		
VIN:	4DRBUAAN8BB334938	License Number:	74847	Bus Number:	43		
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	B	Mileage:	104904				
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.