REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	2/25/2015	**Time:**	8:28 AM
Name of School Corporation:		NORTH LAWRENCE	COMM. SCHOOLS			**Corp ID:**	475075
Address of School Corporation:		595 Stars Blvd					
City:	Bedford	**Zip:**	47421			**County Number:**	47
VIN:	4DRBUAAP18A499505			**License Number:**	B267D	**Bus Number:**	4SH
Make of Body:	IC Corporation	**Year:**	2008	**Make of Chassis:**	IC Corporation	**Year:**	2008
Bus Type:	C			**Mileage:**	126380		
Inspection Status:	O	**Inspected By:**	Travis Coryea			**PE:**	5892

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.