

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/25/2015	<b>Time:</b> 8:37 AM
<b>Name of School Corporation:</b> SOUTH DEARBORN COMM. SCH. CORP	<b>Corp ID:</b> 151600	
<b>Address of School Corporation:</b> 6109 Squire Place		
<b>City:</b> Aurora	<b>Zip:</b> 47001	<b>County Number:</b> 15
<b>VIN:</b> 1HVBBAAP6XH677032	<b>License Number:</b> 2563	<b>Bus Number:</b> 5A
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 1999	<b>Mileage:</b> 181272	<b>Year:</b> 1999
<b>Bus Type:</b> B		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
22-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire

#### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.