REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Post-Crash In | spection | Date: | 2/24/2015 | Time: | 10:37 AM |
|--------------------------------|-------------------|--------------|--------------------------|---------------------|---------------|----------|
| Name of School Corporation: | | SOUTH VERMIL | LION COMM SCH C | N COMM SCH CORP | | 838020 |
| Address of School Corporation: | | PO Box 38 | 87 | | | |
| City: | Clinton | Zip: | 47842 | | County Number | 83 |
| VIN: | 4DRBUSKPX9B690405 | | License Numb | ber: 31513 | Bus Number: | 15 |
| Make of Body: | IC Corporation | Year: 2009 | Make of Chase | sis: IC Corporation | Year: | 2009 |
| Bus Type: | С | | Mileage: | 81522 | | |
| Inspection Status: | А | Inspected | By: Tyler VanNess | | PE: | 7583 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.