

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/11/2015	Time:	11:02 AM
Name of School Corporation:	SAINT JOAN OF ARC & ST PATRICK SCH			Corp ID:	34B395
Address of School Corporation:	3155 S CR 200W				
City:	Kokomo	Zip:	46902	County Number:	34
VIN:	4DRBUAAP5DB077371	License Number:	B595B	Bus Number:	113
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation
Year:	2011	Year:	2011	Year:	2011
Bus Type:	C	Mileage:	8441	PE:	7018
Inspection Status:	R	Inspected By:	Randy McPike		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.