

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/11/2015	Time:	12:42 PM
Name of School Corporation:	NETTLE CREEK SCHOOL CORP.	Corp ID:	898305		
Address of School Corporation:	795 Baker Rd				
City:	Hagerstown	Zip:	47346	County Number:	89
VIN:	4drbuskp2eb417632	License Number:	7009	Bus Number:	27
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
Year:			2012	Year:	2012
Bus Type:	C	Mileage:	18373		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.