

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 3/11/2015 Time: 12:42 PM
Name of School Corporation: NETTLE CREEK SCHOOL CORP. Corp ID: 898305
Address of School Corporation: 795 Baker Rd
City: Hagerstown Zip: 47346 County Number: 89
VIN: 4drbuskp2eb417632 License Number: 7009 Bus Number: 27
Make of Body: IC Corporation Year: 2014 Make of Chassis: IC Corporation Year: 2012
Bus Type: C Mileage: 18373
Inspection Status: O Inspected By: Jeremy Mason PE: 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.