REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/12/2015 **Time:** 11:06 AM **Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1145550License Number:2370Bus Number:21Make of Body:Star Trans Year:2010Make of Chassis:Chevrolet Year:2010

Bus Type: Mileage: 32755

Inspection Status: A Inspected By: Bradley Miller PE: 7809

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description