REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	3/17/2015	Time:	3:04 PM
Name of School C	•	SOU		COMM. SCH. CO	ORP	Corp ID:	313190
Address of School Corporation:			315 S Harriso				
City:	Corydon		Zip:	47112		County Number:	31
VIN:	1HVBBABP31H4019	932		License Number:	18241	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year:	2001	Make of Chassis:	IC Corporation	Year:	2001
Bus Type:	С			Mileage:	120740		
Inspection Status:	: 0		Inspected By:	Troy Boyd		PE:	5171

Violations - Rejected

24-1-1

Inspection Code

<u>Description</u>

The bus body has rust or rusted through areas which may weaken the body

Violations - Out of Service

Inspection Code	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.