

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/21/2015	Time:	6:29 AM		
Name of School Corporation:	SEYMOUR COMMUNITY SCHOOLS			Corp ID:	363675		
Address of School Corporation:	1638 S Walnut St						
City:	Seymour	Zip:	47274	County Number:	36		
VIN:	4DRBUAFN76B206785		License Number:	281	Bus Number:	30	
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	C			Mileage:	116860		
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.