## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Spot ChecksDate:4/6/2015Time:1:23 PMName of School Corporation:NORTH WEST HENDRICKS SCHOOLSCorp ID:323295

Address of School Corporation: PO Box 70

City:LiztonZip:46149County Number:32VIN:4DRBUAFP98B556794License Number:B427cBus Number:18Make of Body:AmTran Year:2008Make of Chassis:IC Corporation Year:2008

Bus Type: C Mileage: 61342

Inspection Status: R Inspected By: Edwin Davis PE: 3981

Violations - Rejected

Inspection Code Description

23-1-3 Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.