

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 4/7/2015	Time: 8:46 AM
Name of School Corporation: VALPARAISO COMMUNITY SCHOOLS	Corp ID: 646560	
Address of School Corporation: 55 Evans St		
City: Valparaiso	Zip: 46383	County Number: 64
VIN: 4DRBWAAN4AA192148	License Number: 33109	Bus Number: 58
Make of Body: IC Corporation	Year: 2010	Make of Chassis: IC Corporation
Year: 2010	Mileage: 66001	Year: 2010
Bus Type: D		
Inspection Status: O	Inspected By: Nathan Sherer	PE: 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
70-1-2	There are intersecting cracks in the windshield area covered by the wipers

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
63-2-3	Any tire is flat
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.