## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	4/9/2015	Time:	11:18 AM
Name of School Co	orporation: EAST	ALLEN COUN	TY SCHOOLS		Corp ID:	20255
Address of School	Corporation:	1322 Green Ro	k			
City:	New Haven	Zip:	46774		<b>County Number:</b>	2
VIN:	4DRBUAFN75B9794	16	License Number:	7321	Bus Number:	123
Make of Body:	IC Corporation Year:	2005	Make of Chassis:	IC Corporation	Year:	2005
Bus Type:	С		Mileage:	126216		
Inspection Status:	R	Inspected By:	Eric Egbert		PE:	7006

## **Violations - Rejected**

Inspection CodeDescription13-1-1Any clearance light is missing, cracked, faded, wrong color, or inoperative

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.