REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: Annual | | | Date: | 4/16/2015 | Time: | 7:41 AM |
|-----------------------------|---------------------|---------------|------------------|----------------|----------------|---------|
| Name of School Corporation: | | ON TOWNSHIP | SCHOOL CORP | | Corp ID: | 646530 |
| Address of School | Corporation: | 599 W 300 N A | A | | | |
| City: | Valparaiso | Zip: | 46385 | | County Number: | 64 |
| VIN: | 1HVBBABPXXH253 | 626 | License Number: | 17201 | Bus Number: | 11 |
| Make of Body: | IC Corporation Year | : 1999 | Make of Chassis: | IC Corporation | Year: | 1999 |
| Bus Type: | С | | Mileage: | 153899 | | |
| Inspection Status: | 0 | Inspected By: | Dale Morgan | | PE: | 4743 |

Violations - Rejected

| Inspection <u>Code</u> | Description |
|---------------------------|--|
| 28-1-4 | The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction. |
| 16-1-1 | There are any leaks from the differential, pinion seal, or either rear wheel seal |

Violations - Out of Service

| Inspection <u>Code</u> | Description |
|---------------------------|---|
| 8-2-12 | There is any defect, which the inspector feels would adversely affect the ability of the vehicle to stop safely |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.