REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/17/2015 Time: 8:01 AM

Name of School Corporation: HANOVER COMM. SCHOOL CORP.

Corp ID: 454580

Address of School Corporation: PO Box 645

City: Cedar Lake Zip: 46303 **County Number: 45** VIN: 4DRAPSKK89A666780 **Bus Number:** License Number: 32985 21 Make of Body: Make of Chassis: IC Corporation Year: 2009 IC Corporation Year: 2009

Bus Type: С Mileage: 58355

PE: **Inspection Status:** R **Inspected By:** Dale Morgan 4743

Violations - Rejected

Description **Inspection Code**

62-1-2 One (1) taillight or one (1) brake light does not function

2-1-1 Required back-up lights do not function.

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.