

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/17/2015	Time:	10:40 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635
Address of School Corporation:	35 W 3rd St				
City:	Peru	Zip:	46970	County Number:	52
VIN:	4UZABRDT6DCFE2497	License Number:	5044	Bus Number:	7
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	44483
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

## Violations - Rejected

## Inspection Code Description

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.