## REPORT OF SCHOOL BUS INSPECTION

Type of 12:26 4/22/2015 **Time**: Re-Inspection Date: Inspection: PM **BLUE RIVER VALLEY SCHOOLS** Name of School Corporation: 333405 Corp ID: **Address of School Corporation:** PO Box 217 County City: Mount Summit Zip: 47361 33 Number: License VIN: 1GBL7T1E92J515178 19248 **Bus Number:** 15 Number: Make of Blue Bird Year: 2003 GMC 2002 Make of Body: Year: Corporation Chassis: **Bus Type:** С Mileage: 137419 Inspected PE: **Inspection Status:** R Jeremy Mason 8139 By:

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.