REPORT OF SCHOOL BUS INSPECTION

Type of 11:16 Time: Annual Date: 4/27/2015 Inspection: AM Name of School Corporation: SOUTHEAST FOUNTAIN SCHOOL CORP 232455 Corp ID: **Address of School Corporation:** 744 E US 136 County City: Veedersburg Zip: 47987 23 Number: License VIN: 4UZABRDUX8CZ11040 7752 Bus Number: 10 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2008 Chassis: Inc. Bus Type: C Mileage: 39600 Inspection Inspected 0 PE: Nate King 7421 Status: By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection</u>	Description
Code	<u>Description</u>

Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.