

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/29/2015 **Time:** 7:49 AM
Name of School Corporation: UNION TOWNSHIP SCHOOL CORP **Corp ID:** 646530
Address of School Corporation: 599 W 300 N A
City: Valparaiso **Zip:** 46385 **County Number:** 64
VIN: 1GDHG31F0X1136891 **License Number:** 38367 **Bus Number:** A4
Make of Body: GMC **Year:** 1999 **Make of Chassis:** GMC **Year:** 1999
Bus Type: **Mileage:** 82110
Inspection Status: O **Inspected By:** Dale Morgan **PE:** 4743

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1 There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description