

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/30/2015	Time: 8:54 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 4DRBUSKN69B095307	License Number: 30874	Bus Number: 22
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation
Year: 2009	Mileage: 87902	Year: 2009
Bus Type: C		
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.