

# REPORT OF SCHOOL BUS INSPECTION

|                                |                              |                 |           |                  |           |
|--------------------------------|------------------------------|-----------------|-----------|------------------|-----------|
| Type of Inspection:            | Annual                       | Date:           | 5/4/2015  | Time:            | 9:35 AM   |
| Name of School Corporation:    | EDINBURGH COMM. SCHOOL CORP. | Corp ID:        | 414215    |                  |           |
| Address of School Corporation: | 202 S Keeley St              |                 |           |                  |           |
| City:                          | Edinburg                     | Zip:            | 46124     | County Number:   | 41        |
| VIN:                           | 1GBJB31K691164088            | License Number: | 81391     | Bus Number:      | 10        |
| Make of Body:                  | Collins Bus Corporation      | Year:           | 2009      | Make of Chassis: | Chevrolet |
| Bus Type:                      |                              | Mileage:        | 23100     | Year:            | 2009      |
| Inspection Status:             | A                            | Inspected By:   | John Pang | PE:              | 6196      |

## Violations - Rejected

## Inspection Code Description

## Violations - Out of Service

## Inspection Code Description

## Bus Type Description