

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/13/2015	Time:	10:24 AM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS	Corp ID:	111125		
Address of School Corporation:	PO Box 169				
City:	Knightsville	Zip:	47857	County Number:	11
VIN:	4UZABRDT3ECFK1791	License Number:	6407	Bus Number:	10
Make of Body:	Thomas Built Buses, Inc.	Year:	2014	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	38850		
Inspection Status:	O	Inspected By:	Tyler VanNess	PE:	7583

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
75-1-5	Fan is loosely attached or wobbles
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
70-1-4	There is any cracked glass to the immediate right or left of the driver
51-1-2	Protective padding is missing or damaged
51-1-1	Any door seals are missing, damaged, or torn
64-1-4	Any front turn signal does not function properly
69-1-2	Wiper blades fail to contact the windshield properly
36-1-1	The latch does not secure the hood tightly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.