REPORT OF SCHOOL BUS INSPECTION

9:53 Type of Time: Re-Inspection Date: 5/8/2015 Inspection: AM BARTHOLOMEW CONS. SCHOOL CORP. 30365 Name of School Corporation: Corp ID: **Address of School Corporation:** 1260 N Marr Rd County City: Columbus Zip: 47201 3 Number: License VIN: 1BAANCPAX3F212163 19230 Bus Number: 232 Number: Make of Blue Bird Blue Bird Year: 2003 Make of Body: Year: 2003 Corporation Chassis: Corporation

Bus Type: D Mileage: 177745

Inspection O Inspected Travis Coryea PE: 5892
Status: PE: 5892

Violations - Rejected

Inspection Code Description

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

59-2-3 Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.