

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 5/18/2015 **Time:** 10:08 AM
Name of School Corporation: RENNELAER CENTRAL SCHOOL CORP **Corp ID:** 373815
Address of School Corporation: 900 E Washington
City: Rensselaer **Zip:** 47978 **County Number:** 37
VIN: 1GBJG316X91164744 **License Number:** MO76930 **Bus Number:** 09
Make of Body: Collins Bus Corporation **Year:** 2009 **Make of Chassis:** Chevrolet **Year:** 2009
Bus Type: **Mileage:** 135810
Inspection Status: O **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-2	LED type lights have 50% or more of the pixels inoperative in any one rear light
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description