

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/18/2015	Time:	9:14 AM		
Name of School Corporation:	PAOLI COMMUNITY SCHOOL CORP.	Corp ID:	596155				
Address of School Corporation:	501 S Elm St						
City:	Paoli	Zip:	47454	County Number:	59		
VIN:	1FDWE35F53HB43716		Licence Number:	66045	Bus Number:	A3	
Make of Body:	Collins Bus Corporation	Year:	2004	Make of Chassis:	Ford	Year:	2004
Bus Type:	A1			Mileage:	62112		
Inspection Status:	O	Inspected By:	Mike Adams	PE:	7407		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-3	One (1) nut, bolt or lug is missing, loose or broken
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
70-1-4	There is any cracked glass to the immediate right or left of the driver
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.