## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			Date:	5/18/2015	Time:	9:14 AM
Name of School Corporation: Address of School Corporation:		PAOL	I COMMUNITY 501 S Elm St	SCHOOL CORP.		Corp ID:	596155
City:	Paoli		Zip:	47454		County Number:	59
VIN:	1FDWE35F53HB4371	6		License Number:	66045	Bus Number:	A3
Make of Body:	Collins Bus Corporation	Year:	2004	Make of Chassis:	Ford	Year:	2004
Bus Type:	A1			Mileage:	62112		
Inspection Status:	0		Inspected By:	Mike Adams		PE:	7407

## **Violations - Rejected**

Inspection Code	<u>Description</u>
67-1-3	One (1) nut, bolt or lug is missing, loose or broken
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
70-1-4	There is any cracked glass to the immediate right or left of the driver
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

## **Violations - Out of Service**

	ection ode	<u>Description</u>
63-2	:-3	Any tire is flat
24-2	:-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2	-2	Any body surface protrudes beyond the normal limits of the body structure

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
   Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.