REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 6/2/2015	**Time:**	9:18 AM
Name of School Corporation:	LEARNING LAND DAY CARE			**Corp ID:**	55002Z
Address of School Corporation:	960 S. Marion St				
City:	MARTINSVILLE	**Zip:**	46151	**County Number:**	55
VIN:	1GDHG31R6Y1229751		**License Number:** B831L	**Bus Number:**	1
Make of Body:	Girardin Minibus, Inc. **Year:**	2000	**Make of Chassis:** GMC	**Year:**	2000
Bus Type:			**Mileage:** 54561		
Inspection Status:	O	**Inspected By:**	Mark Raper	**PE:**	6473

Violations - Rejected

Inspection Code	Description
25-1-1	Mirror or mirror backs that are loose or improperly mounted

Violations - Out of Service

Inspection Code	Description
64-2-2	LED type lights have 50% or more of the pixels inoperable in any one rear light

Bus Type Description