REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/1/2015	**Time:**	9:48 AM
Name of School Corporation:	BLUE RIVER SERVICES			**Corp ID:**	450001
Address of School Corporation:	3141 Progress Blvd.				
City:	Corydon	**Zip:**	47112	**County Number:**	31
VIN:	1GBJG31U351244007	**License Number:**	68708	**Bus Number:**	93
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A2	**Mileage:**	123162		
Inspection Status:	R	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**